

# Oil Field Environmental Incident Summary

**Incident:** 20141031161451 **Date/Time of Notice:** 10/31/2014 16:14

**Responsible Party:** Clean Energy Fluids Systems LLC

**Well Operator:** KEY ENERGY SERVICES, LLC

**Well Name:** GEORGE TANK 1

**Field Name:** CAMEL BUTTE

**Well File #:** 3680

**Date Incident:** 10/30/2014 **Time Incident:** 15:28

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151

**Rng:** 96

**Sec:** 27

**Qtr:** NE SE

**Location Description:** Frac Tanks south of plant location

**Submitted By:** Steven Alderin

**Received By:**

**Contact Person:** Steven Alderin  
1301 MCKINNEY  
STE 1800  
HOUSTON, TX 77010

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1200 Feet

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	10	Barrels	3	barrels
Other						

**Description of Other Released Contaminant:**

None

**Inspected:**

**Written Report Received:** 12/14/2015

**Clean Up Concluded:** 12/10/2015

**Risk Evaluation:**

No Risk

**Areal Extent:**

None

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Plan of action is to remove tanks

**Wastes Disposal Location:** Clean Energy Fluids Systems LLC

**Agencies Involved:**

**Updates**

---

**Date:** 10/31/2014 **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow, is reported to be "south of the plant location" within the diking. Wording is ambiguous as to whether the frac tank was on the plant location, so followup is necessary.

---

**Date:** 11/4/2014 **Status:** Inspection

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

11/4/14 - 16:00 on location. Three portable frac tanks (yellow Sikanni) south of the lease road in small lined berm. Brine overflow also flowed out of the NW corner of the containment into the loading area. When tanks and liner are removed, additional impact will need to be removed in the area outside the containment, and confirmation sample will need to be collected.

---

**Date:** 12/12/2014 **Status:** Awaiting Documentation

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On 12/11, 16:19 - received email from company contact. Email as follows:

We have taken the frac tanks out of service, and they are no longer on the facility. We have yet to tear the berm down. Now that we have had a break in the weather, I will have the guys get it taken down this weekend and get pictures, along with samples gathered, so we can close this case.